

IN THE DRAWING

Four (4) replacement sheets of drawing are submitted herewith, bearing Figs. 47 and 49-51, and are to be substituted for the corresponding original sheets of drawing.



FIG. 47




FIG. 49

3430

COPY

SEND

RETRIEVE

TASKS

MGMT

CONFIG

WWW

E-Mail

Fax

FTP Server

Server

3431

Long Name

Password

3433

☐ Delete From Server

☐ Put Into HD

Print Setting

LTAR

300dpi

100%

Status

3402

36/60

FIG. 50

3440

COPY

SEND

RETRIEVE

TASKS

MGMT

CONFIG

WWW

E-Mail

Fax

FTP Server

Fax Number

3441

Put Into HD

Print Setting

LTAR 300dpi 100%







Status


3403


37/60


FIG. 51


3450

COPY  SEND  RETRIEVE  TASKS  MGMT  CONFIG 

WWW 

E-Mail 

Fax 

FTP Server 

Server

3451

Long Name

Password

3453

3452

☐ Delete From Server

3454

☐ Put Into HD

Print Setting

LTAR

300dpi

100%

Status

3404